

FIG. 1 - Prior Art






FIG. 2 - Prior Art

Replacement sheet

2/3



where $H_1, H_2, H_3, \dots, H_m$ are given by:

$$H_i(z) = \frac{1 - az^{-1}}{1 - bz^{-1}}$$

$|a|$ and $|b|$ are < 1
 a and b have the same sign

OR BY

$$H_i(z) = \frac{1 - 2g_i \cos(P_i)z^{-1} + g_i^2 z^2}{1 - 2r_i \cos(P_i)z^{-1} + r_i^2 z^2}$$

FIG. 4





FIG. 5